

# Oil Field Environmental Incident Summary

**Incident:** 20160922084417      **Date/Time of Notice:** 09/22/2016 08:44

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** WAYZETTA 28-1424 CTB

**Field Name:** PARSHALL

**Well File #:**

**Date Incident:** 9/21/2016      **Time Incident:** 10:20      **Facility ID Number:** 225749-01

**County:** MOUNTRAIL      **Twp:** 153      **Rng:** 90      **Sec:** 14      **Qtr:** NW NE

**Location Description:** Misted area off site was about a 200 sq. ft. area.

**Submitted By:** Brenda Vaness

**Received By:**

**Contact Person:** Brenda Vaness  
600 17TH ST STE 1000N  
DENVER, CO 80202

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Gallons	5	Gallons	5	gallons

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/3/2017

**Clean Up Concluded:** 9/22/2016

**Risk Evaluation:**

N/A

**Areal Extent:**

**Potential Environmental Impacts:**

N/A

**Action Taken or Planned:**

Residual liquids were soaked up with absorbent pads, and burnt up gravel on site will be remediated. Landowner contact has been made to discuss off site clean-up of 200 sq. ft. area misted on cultivated field.

**Wastes Disposal Location:** Remediated on site

**Agencies Involved:**

**Updates**

---

**Date:** 9/22/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 9/22/2016.

Minimal amount of material left location to the SW of the flare. Company personnel were on location and in the process of cleaning up the site. Minimal impacts to surrounding area.

No follow-up is necessary.

---

**Date:** 9/22/2016    **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release impacted areas off location. Follow-up is required.